

TJC and Associates, Inc.

Product Revision Numbers (Rev 1.44)

Product Number	Latest Revision Number	Number of Sheets	Status
303001-3	7.00.0	23	Active
30405	3.0.0	10	Active
306020	2.00.1	13	Active
312003	0.00	5	Active
312003LS	0.02.0	5	Active
312003LS	0.03.0	5	Active
316001	0.00.0	8	Active
500002-LRP 2415	5.00	2	Active
500002-LRP 2420	5.00	2	Active
503032-LRP-2415A	8.00	5	Active
503032-LRP-3215A	7.00	3	Active
50335 OSB-02415	6.00	2	Active
506027-CA-LRP 02410	6.00	2	Active
507001-CA-LWP VIN1.0VIN	3.00	1	Active
507033 CA-LWP BDB1.0LUR	4.00	1	Active
511013 CA-LWP-VIN20VIN	3.00	1	Active
512004-CA-LWP 080-2.0PI/1.0EPS	2.00	1	Active
512005-LRP-2410	3.00	2	Active
512005-NY-LWP10	1.00	1	Active
512005-OSB-2410	1.00	2	Active
804015 CA-LRP 01920	5.00	2	Active
804015 CA-LRP 03220	6.00	2	Active
804015 CA-LWP THB20THB/LN	6.00	1	Active
804015 CA-SIP 71610	5.00	2	Active
807003 CSP-1	5.00	1	Active
807008 CA-LRP 2410	6.00	2	Active
807008 CA-LRP 2415	3.00	2	Active
807008 CA-LRP 3220	5.00	2	Active
807008 CA-LWP-THB10THB/LN	4.00	1	Active
807008 IBC-LRP 2410	3.00	2	Active
807008 IBC-LRP-3020	4.00	2	Active
814001 CA-LRP 2410	3.00	2	Active
814001 CA-LRP 2420	3.00	2	Active
814001 CA-LWP VIN1.5VIN	2.00	1	Active

Note: Changes to the last digit of a revision number are editorial in nature and do NOT reflect an engineering change. Therefore, from an engineer prospective, revision 4.01 is identical to revision 4.08.

TJC and Associates, Inc.
Product Revision Numbers (Rev 1.44)

Product Number	Latest Revision Number	Number of Sheets	Status
10208	2.00	2	Expired
10215	6.2.3	19	Expired
19805	--	8	Expired
19918	--	11	Expired
19930	2.00	7	Expired
30304	4.20	22	Expired
30407	DRAFT	N/A	Expired
30507	1.22	10	Expired
30522	0.3.0	9	Expired
304015	0.00	8	Expired
306019	0.30	8	Expired
306022	0.00	8	Expired
307003	2.01	16	Expired
308021	3.03.0	7	Expired
306019-SL	0.00	1	Expired
306022-SL	0.00	1	Expired
50025-LRP-2415	2.00	1	Expired
50025-LRP-3215	2.00	1	Expired
50124B-CA-LWP VIN20VIN	2.00	1	Expired
502019 CA-LWP-18-20PI	4.00	1	Expired
502019 CA-LWP-LAS-20PI	2.00	1	Expired
502019-CA-LWP-1810	4.00	1	Expired
502019-CA-RFP-LAS-20PI	2.00	1	Expired
50215-CA-LWP	5.00	1	Expired
50215-LRP-2415	3.00	2	Expired
503047-LRP 2420	3.00	2	Expired
50335 OSB-02410	2.00	3	Expired
50340A-LRP-2415	3.00	1	Expired
504026 LRP-2410B	3.00	2	Expired
504026 LRP-2415B	2.00	3	Expired
504026 OSB-2410	3.00	2	Expired
505018-CA LWP THB15LN	2.00	1	Expired
505032-CA LWP 18-20PI	3.00	1	Expired
506001-20 XEPS	1.00	2	Expired
506001-LRP 20HC	1.00	2	Expired
506002-CA LWP VIN EPS VIN	0.00	1	Expired
507002-CA-LRP 02410	0.00	2	Expired
507002-CA-LRP 02415	0.00	2	Expired
507003 CA-LWP-VIN	3.00	1	Expired
510014 CA-LRP 2410	2.00	2	Expired
511007 CA-LRP 2420	1.00	2	Expired
511013 CA-LWP-VIN20PIVIN	1.00	1	Expired
804001B-CA-LRP 03220	3.00	2	Expired
804001B-CA-LWP THB10THB/LN	2.00	1	Expired
804001B-CA-LWP THB20PI THB/LN	2.00	1	Expired
804001B-CA-SIP 71610	2.00	2	Expired
804008B-CA-LWP 18-15	5.00	1	Expired
804019 CA-LRP 2410	1.00	1	Expired
804019 CA-LRP 2420PI	1.00	2	Expired
807008 CA-LWP-THB20PI THB/LN	2.00	1	Expired
807008 CA-SIP 71610	1.00	2	Expired
807008 IBC-LRP 3220	0.00	2	Expired
807025 CA-SIP 71610	1.00	2	Expired
814002 CA-LRP 2410	0.00	2	Expired

Note: Changes to the last digit of a revision number are editorial in nature and do NOT reflect an engineering change. Therefore, from an engineer prospective, revision 4.01 is identical to revision 4.08.